

Request List

General Items

Comments

Buyer Requests "xxxxx"

Roof Materials

(RCG-1) Major Concern :

The headwall flashing has separated from the wall, creating a pathway for moisture to enter the structure. Signs of moisture damage are noted on the interior beneath this section. A qualified roofing contractor should repair or replace the flashing to restore proper weather protection.



Redemption Value: \$0.00